

## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street  
Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

## FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-1115

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Manchester

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent ( ) Good (X)  
Fair ( ) Poor ( )

THEME:

STYLE:

DATE BUILT: late 19th c.

COUNTY: CARROLL  
TOWN: MEL ROSE

LOCATION: 4204 HANOVER PIKE (MD 30)

COMMON NAME:

FUNCTIONAL TYPE: Residence

OWNER: Oscar Wentz  
ADDRESS: 4204 Hanover Pike  
Manchester Md 374-6892ACCESSIBILITY TO PUBLIC:  
Yes ( ) No (X) Restricted ( )LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

## GENERAL DESCRIPTION:

## Structural System

1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
  2. Wall Structure
    - A. Wood: Log (X) Post and Beam ( ) Balloon ( )
    - B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
    - C. Iron ( ) D. Steel ( ) E. Other
  3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum (X) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
  4. Roof Structure
    - A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
    - B. Other:
  5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle (X) Sheet Metal ( )  
Built Up ( ) Rolled ( ) Tile ( ) Other:
  6. Engineering Structure:
  7. Other:
- Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells (X) Wings ( ) Other:
- Roof Style: Gable ( ) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:
- Number of Stories: 2  
Number of Bays: 2 x 2  
Approximate Dimensions: \_\_\_\_\_
- Entrance Location: \_\_\_\_\_

## THREAT TO STRUCTURE:

No Threat (X) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

## LOCAL ATTITUDES:

Positive (X) Negative ( )  
Mixed ( ) Other:

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

modern renovations have altered historic appearance of this structure  
aluminum siding, enclosed porch

## RELATED STRUCTURES: (Describe)

frame washhouse at rear of structure  
frame chicken house and tool shed on property

## STATEMENT OF SIGNIFICANCE:

contributing structure

## REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas:

## SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up ( ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

## RECORDED BY:


Joe Getty

## ORGANIZATION:

C. C. Dept. of Planning

## DATE RECORDED:

7/85



MANCHESTER, MD-PA.

QUADRANGLE

7.5 minute series



1. CARR-1115
2. Carroll County, Maryland
3. Joe Getty
4. July 1985
5. Maryland Historical Trust, Annapolis, Md.
6. East elevation (camera facing west)
7. 1/1